

<p>INCREASING HARDNESS</p>		<b>1</b>	TALC	
		<b>2</b>	GYPSUM	← FINGERNAIL (2.5)
		<b>3</b>	CALCITE	← COPPER COIN (3.5)
		<b>4</b>	FLUORITE	
		<b>5</b>	APATITE	← IRON / GLASS (5.5)
		<b>6</b>	FELDSPAR	
		<b>7</b>	QUARTZ	← STEEL (6.5)
		<b>8</b>	TOPAZ	
		<b>9</b>	CORUNDUM	
		<b>10</b>	DIAMOND	